



2017 E300W

Grade:
4.3

Vehicle Options

AMG Body Cladding
Sport Exterior
Sport Wheel Package
Burmester Premium Sound System
Blind Spot Assist
Comfort Headrests/Front
Natural Grain Black Ash Wood
Rear Deck Spoiler
Sport Interior
KEYLESS-GO
Air Balance Package
Heated front seats plus
Black Roof Liner
Wheel Locking Bolts
3-spoke multifunction steering wheel
Power Rear-Window Sunshade
Hands-Free Access
Electronic Trunk Closer
Comfort Box
Rearview Camera
Premium 2 Package
NFC Wireless Charging
PARKTRONIC (with Advanced Parking Assist)
SIRIUS Satellite Radio
Intelligent Highbeam Control
19" AMG 5-twin-spoke alloy wheels
Lighting Package
Keyless Go Comfort Pack
Sport-tuned suspension for Sport

VIN: WDDZF4JB7HA109984	Location: Manheim San Francisco Bay
Miles: 21,363 miles	Seller : MBFS
Exterior: Iridium Silver Metallic	Title State: CA
Interior: Black MB-Tex	Warranty Date: 08-16-17
Engine:	Drive:
Odor: OK	MSRP: \$63,395
Announcements: DMV\$220	
Value Added Options: Sport Package , Electric Trunk Close , Keyless Go , Parktronic , Blind Spot Assist , Lighting Package , Rear View Monitor , Multi Contour Seats , Variable Heated Seats	

Vehicle Condition

Tire	Tread	Brand	Size
LFRNT"	3	GOODYEAR	245/40R19
LREAR"	4	GOODYEAR	245/40R19
RFRNT"	3	GOODYEAR	245/40R19
RREAR"	3	GOODYEAR	245/40R19
SPARE"			

Damages	Condition	Severity
F Bumper Center Molding>	Broken	Replacement Required
Hood>	Mult Dents/No Paint Dmg	PDR/2
LF Tire>	Worn eagle sport 98v	Replacement Required
RF Tire>	Worn eagle sport 98v	Replacement Required
RR Door>	Dent/No Paint Dmg	PDR/1
RR Tire>	Worn eagle sport 98v	Replacement Required
Warning - Maintenance>	On	Unacceptable
Navigation System>	Clear History	Needs Clearing
Console Cover>	Scratch Light	6" to 7"

Repaired	Condition	Severity	Repair Type
----------	-----------	----------	-------------

Perforated front brake discs & front brake calipers
Active Multicontour Seats
LED Intelligent Headlamps

Front Bumper Cover	Curb Rash	Repaired	Repair
R Bumper Textured	Broken	Repaired	Replace
Front Emblem	Broken STAR	Repaired	Replace
LF Wheel	Curb Rash	Repaired	Repair
LR Wheel	Curb Rash	Repaired	Repair
Rear Bumper Cover	Heavy Mult Scratches	Repaired	Repair
Rear Bumper Center Molding	Broken CHROME	Repaired	Replace
RF Wheel	Curb Rash	Repaired	Repair
R Rocker Panel Molding	Dent/Paint Dmg	Repaired	Repair
RR Wheel	Curb Rash	Repaired	Repair

Key
Smart Key - 2