



## Vehicle Options

Single DVD Player
KEYLESS-GO
Black Fabric Headliner
Android Auto
Trailer Hitch
Blind Spot Assist
Region Coding
Heated Steering Wheel
Apple CarPlay
Lane Keeping Assist
Premium 1 Package
Smartphone Integration
19" 5-Spoke Wheels
Navigation Map Updates included for 3-years
SiriusXM Radio w. 6 mos. service
Pre-Wiring for Rear Seat Entertainment
Wheel Locking Bolts
Anthracite Poplar Wood
115V AC Power Outlet
Rearview Camera
Lane Tracking package code
COMAND Navigation
harman/kardon LOGIC7 Surround Sound System

# 2018 GLE350W4

**Grade:**  
**3.5**

**VIN:** 4JGDA5HB2JB118909

**Location:** Manheim Pennsylvania

**Miles:** 16,595 miles

**Seller :** MBFS

**Exterior:** Black

**Title State:** PA

**Interior:** Black MB-Tex

**Warranty Date:** 07-02-18

**Engine:**

**Drive:**

**Odor:** Foul

**MSRP:** \$60,900

**Announcements:** PROGRAM INELIGIBLE , Previous Paintwork,\* LOCATED AT 75 GRACE BLVD MORGANTOWN PA,\*\* Not eligible for Remarketing incentives \*\*

**Value Added Options:** Keyless Go , Blind Spot Assist , Lane Keep Assist , Rear View Monitor , Smart Phone Integration , Navigation System

## Vehicle Condition

Tire	Tread	Brand	Size
LFRNT"	8	CONTINENTAL	255/50R19
LREAR"	8	CONTINENTAL	255/50R19
RFRNT"	7	CONTINENTAL	255/50R19
RREAR"	8	CONTINENTAL	255/50R19
SPARE"		(Mini)	

Damages	Condition	Severity
Windshield>	Star in Glass	1/8" to 1/2"
Lift Gate>	Prev Repair	Substd Repair
LF Seat Bolster>	Stained	Permanent
RF Seat Bolster>	Stained	Permanent
Front Bumper Cover>	Chipped	10 or More
F Bumper Center Molding>	Chipped	10 or More
Grille - Chrome>	Chipped	10 or More
L Headlight>	Chipped	Replacement Required
R Headlight>	Chipped	Replacement Required
Hood>	Chipped	9

LF Wheel>	Curb Rash	5" to 6"
LR Door>	Dent/No Paint Dmg	PDR/1
Liftgate Trim Panel Trim/Mld>	Heavy Mult Scratches	10 or More
Rear Bumper Cover>	Replaced	Acceptable
R Bumper Step Pad>	Heavy Mult Scratches	10 or More
RF Wheel>	Curb Rash	2" to 3"
RR Door>	Dent/No Paint Dmg	PDR/1
RR Wheel>	Curb Rash	2" to 3"
Multi-Function Switch>	Broken	Replacement Required
LF Door Panel>	Heavy Mult Scratches	5
Console>	Heavy Mult Scratches	10 or More
Console RR Vent Register>	Broken	Replacement Required

### Key

Master Key - 2

Smart Key - 1