



Vehicle Options

AIRSCARF - Ventilated Headrest
Burl Walnut Wood Trim
SIRIUS XM Satellite Radio
Rear Deck Spoiler
Premium 2 Package
KEYLESS-GO
Apple CarPlay
Wheel Locking Bolts
harman/kardon LOGIC7 Surround-Sound System
Heated Front Seats
Pre-wiring Satellite Radio
18" 5-Spoke Wheel
Analog Clock on Dashboard
Dual-Zone Automatic Climate Control
Full LED Headlamps
DVD Coding
Panorama Roof
Navigation Map Updates included for 3-years
Blind Spot Assist
Direct Ambient Lighting in SOLAR Red
Dynamic Destination Finding System/Part of COMAND
Adaptive Highbeam Assist
Smartphone Integration

2017 SLC300R

Grade:
4.0

VIN: WDDPK3JA0HF140355	Location: Manheim Riverside
Miles: 7,282 miles	Seller : MBFS
Exterior: Polar White	Title State: HI
Interior: Sahara Beige MB-Tex	Warranty Date: 04-18-17
Engine:	Drive:
Odor: Foul	MSRP: \$57,700
Announcements: DMV\$0	
Value Added Options: Keyless Go , Blind Spot Assist , Lighting Package , Heated Seats - Front , Panorama , Smart Phone Integration , Navigation System	

Vehicle Condition

Tire	Tread	Brand	Size
LFRNT"	6	PIRELLI	225/40ZR18
LREAR"	7	PIRELLI	245/35ZR18
RFRNT"	6	PIRELLI	225/40ZR18
RREAR"	7	PIRELLI	245/35ZR18
SPARE"		(Mini)	

Damages	Condition	Severity
L Qtr Panel>	Scratch Heavy	7" to 8"
L Rocker Panel Molding>	Scratch Heavy	1/8" to 1/2"
LR Tire>	Gouged 92y	Replacement Required
Spoiler>	Scratch Heavy	1" to 2"
Rear Bumper Cover>	Scratch Light	8" to 9"
R Rocker Panel Molding>	Scratch Heavy	1" to 2"
RR Tire>	Gouged 92y	Replacement Required
Glove Box Door>	Broken	Replacement Required
Glove Box Latch>	Broken	Replacement Required

Repaired	Condition	Severity	Repair Type
----------	-----------	----------	-------------

Front Bumper Cover	Scraped	Repaired	Repair
LR Wheel	Curb Rash	Repaired	Repair
RF Wheel	Curb Rash	Repaired	Repair
RR Wheel	Curb Rash	Repaired	Repair

Key

Master Key - 2