



2017 CLS550C

Grade:
4.2

Vehicle Options

Rear Deck Spoiler
Blind Spot Assist
KEYLESS-GO Package Code
Parking Assist Package
3-Spoke Sport Steering Wheel
Active Multicontour Driver Seat
Power Rear-Window Sunshade
Mirror Package (power-folding mirrors)
Night Package
Parking Package (RVC & Parktronic)
Surround View Camera
Night Package
Full LED Headlamps
Premium 2 Package
High-Performance Tires
Split-Folding Rear Seats
Wheel Locking Bolts
KEYLESS-GO
19-Inch AMG 7-Spoke Black Wheels
Heated and Active Ventilated Front Seats
Sportline Package
Black Ash Wood Trim
Power Folding Mirrors
Lane Keeping Assist
Electronic Trunk Closer
Wheel Package
Lane Tracking package code
Intelligent Highbeam Control
PARKTRONIC (with Active Parking Assist)

VIN: WDDLJ7DB6HA197251

Location: Manheim Orlando

Miles: 20,212 miles

Seller : MBFS

Exterior: Black

Title State: FL

Interior: Black Leather w/ white contrast stitching

Warranty Date: 05-31-17

Engine:

Drive:

Odor: OK

MSRP: \$85,050

Announcements: Previous Paintwork, Defective Sunroof

Value Added Options: Night Package , Sport Package , Electric Trunk Close , Keyless Go , Parktronic , Blind Spot Assist , Lane Keep Assist , Lighting Package , Surround View Camera , Multi Contour Seats , Ventilated Seats - Front

Vehicle Condition

Tire	Tread	Brand	Size
LFRTN"	5	PIRELLI	255/35R19
LREAR"	4	PIRELLI	285/30R19
RFRNT"	5	PIRELLI	255/35R19
RREAR"	4	PIRELLI	285/30R19
SPARE"		(Mini)	

Damages	Condition	Severity
Windshield>	Cracked	1/8" to 1/2"
L Headlight>	Cracked SPIDER CRACKS	Replacement Required
Hood>	Dent/No Paint Dmg	PDR/1
Hood>	Chipped	8
Hood>	Light Mult Scratches	4
Roof>	Chipped	3
Warning - Maintenance>	On SRVC B EXCEEDED BY 15 DAY	Unacceptable

Repaired	Condition	Severity	Repair Type
Front Bumper Cover	Curb Rash	Repaired	Repair

Lane Tracking Package

F Bumper Right Molding	Dent/Paint Dmg	Repaired	Replace
Deck Lid	Dent/Paint Dmg	Repaired	Repair
Front Bumper Cover	Gouged melted on L side	Repaired	Included
F Tow Hook Cover	Missing	Repaired	Replace
Deck Lid Ornament	Broken STAR	Repaired	Replace
Rear Bumper Cover	Mult Dents/Paint Dmg	Repaired	Repair
RF Wheel	Curb Rash	Repaired	Repair

Key

Combo Key - 2